

TAYLOR COUNTY MIDDLE SCHOOL



Damaged ceiling tiles throughout school.



Original boilers will be replaced with ones that meet current energy efficiency standards.



DDC controls will be added at the facility to allow individual classroom monitoring.



Heat pumps are twenty-nine years old and have out lived their life expectancy.